

TB193 (Rev1) - How to Create a Report and Backup Files

Introduction

This Tech News will explain how to create a report and how to backup your configuration, CNC files, and ICN files.

CNC7 v6.00+

To backup your configuration, CNC files, and ICN files follow the steps below. In v6.00 Intercon was know as GGE.

```
Insert a blank floppy disk into the control
Press F7 - Utility
Press F3 - Backup
Press F1 - Config (this will backup your configuration files)
and/or
Press F2 - CNC (this will backup your CNC files)
and/or
Press F3 - ICN (this will backup your ICN files)
```

Note: For CNC and ICN files, you can select files by pressing the F1 - Toggle button or the Spacebar. If you would like to backup all files press F2 - All. If the CNC and ICN files are large, they may not fit on 1 disk and will require multiple floppy disks.

To create a report file follow the steps below.

```
Insert a blank floppy disk into the control
Press F7 - Utility
Press F7 - Report
```

CNC10 v1.10 - 1.15

To backup your CNC files and ICN files follow the steps below.

```
Insert a blank floppy disk into the control
Press F7 - Utility
Press F3 - Backup
Press F2 - CNC (this will backup your CNC files)
and/or
Press F3 - ICN (this will backup your ICN files)
Press F1 - Toggle or the SPACEBAR to select individual files
or
Press F2 - All to select all files
Press F10 - Accept
```

Note: If the CNC and ICN files are large, they may not fit on 1 disk and will require multiple floppy disks.

To create a report file follow the steps below.

Insert a blank floppy disk into the control

Press F7 - Utility

Press F7 - Report

CNC10 v1.25 - 1.51

To backup your CNC files and ICN files follow the steps below.

Insert a blank floppy or USB device

Press F7 - Utility

Press F3 - Backup

Press F2 - CNC (this will backup your CNC files)

and/or

Press F3 - ICN (this will backup your ICN files)

Press F1 - Toggle or the SPACEBAR to select individual files

or

Press F2 - All to select all files

Press F10 - Accept

Use the arrow key and highlight either A:Floppy or B:USB Device

Press ENTER to activate the floppy disk or USB device

Press ENTER again to backup the files to the floppy disk or USB device.

Note: If the CNC and ICN files are large, they may not fit on 1 floppy disk and will require multiple floppy disks.

To create a report file follow the steps below.

Insert a blank floppy disk or USB device

Press F7 - Utility

Press F7 - Report

Use the arrow key and highlight either A:Floppy or B:USB Device

Press ENTER to activate the floppy disk or USB device

Press ENTER again to backup the files to the floppy disk or USB device.

CNC10 v2.30+

To create a report file follow the steps below.

Insert a blank floppy disk or USB device

Press F7 - Utility

Press F7 - Report

Use the arrow key and highlight the Destination Directory

Press ENTER to activate the highlighted Destination Directory

Press F10 - Accept to backup the files to that Destination Directory.

Document History

Rev1 Created on **2006-12-07**